

ABSTRACT OF THE DISCLOSURE

A radiation measuring technique includes adjusting a threshold level of a radiation sensor in a radiation-measuring circuit and obtaining an output signal based on radiation dose sensed by the radiation sensor.

30070495.doc